Wyoming Certified Land Corner Recordation Certificate

This form is to be completed in accordance with W.S. 36-11-101, printed in black ink or typed, and shall be for one individual corner.


Describe below, or show in sketch evidence found. Include condition a and ties. Describe any maintenance the circle to the right, show monum is determined lost or obliterated, original field note record; described to reestablish the corner and found monument. Field Date	or rehabilitation performed. In the inscription of monument restate the GLO or BLM be or show the procedure deall data as above for a	/	
EAST /4 COR OF C 9, T 19 N, R 68 W STOCKWELL W/WINDMILL 22.8'	2" BRASS CAP ON 2" GALV. PIPE Along WITH ROCK. MARKED R.L.S. 2097, 1991 NORTHERLY FROM STOCKWELL.	/991 Monument Inscri	RECEI AMIE COI CHEYEN
Office of County Clerk County of ARAM/ This Certified Land Corner Rec	n Book No. T, R he Cross Index Plat. Section(s) 9		day of ric coordinates
Corner Name $G - /3$	Sheet of		•

Directions for using the **Cross Index Plat**

Section, quarter and sixteenth corners will be marked with a dot at the corner location. The alpha-numeric coordinate number is then determined for the intersection of the two lines. A corner that applies to two or more townships shall be filed under all that apply by the use of photo copies.

Closing corners will be indexed under the township in which they control ownership. For 1/64, 1/256, 1/1024 and non-aliquot corners lying between grid designations, mark the appropriate grid area with a dot and use the index code to the north and west (local systems may be used if the method is approved by the County Surveyor or Clerk and a written description of its use is filed in the front of each book of certificates).

Cross Index Plat



State Plane Coordinates (optional)

Zone W	WC	EC	E	feet/meters		≠
☐ NAD 1927		NGV	'D 1929	■ NAD 1983	□ N.	AVD 1988
North (Y) =		1	East (X) =	***	EL = _	
Latitude				Longitude		Crobby
Scale Factor				Geoid Height		

Certification

1. RUSSELL	D .	SCHAMEL	, Wyomin	g PLS-PE	3511	cer
that I, or others under		vision, have performed	the work as described	above and	completed this	s form.
Company or Agency		VEDU EngINEE	RING	<u> </u>		
Mailing Address	P.O.	BOX 1089			اه مسر	Chi
Street Address	606	9 44 ST. #4			nginee	(OIVI)
City, State, ZIP	Who	EATLAND, WY	0. 82201	<u> </u>		LD. SCH
Telephone, FAX	307	- 322-9789	322-9/28		3/2	3511



certify

Signature, Seal, and Date

of Sheet_