
# Wyoming Certified Land Corner Recordation Certificate

This form is to be completed in accordance with W.S. 36-11-101, printed in black ink or typed, and shall be for one individual corner.

Describe below, or show in sketch attached to this form, the corner evidence found. Include condition and type of monument, accessories and ties. Describe any maintenance or rehabilitation performed. In the circle to the right, show monument inscription. If monument is determined lost or obliterated, restate the GLO or BLM original field note record; describe or show the procedure used to reestablish the corner and all data as above for a found monument.

Field Date <u>2-15-90</u> Office Reference <u>90031</u>


Found 2" G.L.O. brass cap on 2" iron pipe, projects 0.2 above ground in N-S fence and 3' north of fence east.



**Monument Inscription** 



State of Wyoming Office of County Clerk County of <u>Laramie</u>



This Certified Land Corner Recordation Certificate was filed for record on the \_\_\_\_\_ day of \_\_\_\_\_\_, 19 \_\_\_\_, in Book No. T \_\_\_\_\_\_, R \_\_\_\_\_\_, on Alpha-Numeric coordinates \_\_\_\_\_\_ and was noted on the Cross Index Plat.


		County Clerk
Corner Type:  Aliquot Corner  Other	Section(s) 9, 10, 15, 16	Meridian 6th P.M.
Corner Name Section	Township 12N	Range 63W Page
	Sheet of	

### Directions for using the Cross Index Plat

Section, quarter and sixteenth corners will be marked with a dot at the corner location. The alpha-numeric coordinate number is then determined for the intersection of the two lines. A corner that applies to two or more townships shall be filed under all that apply by the use of photo copies.

Closing corners will be indexed under the township in which they control ownership. For 1/64, 1/256, 1/1024 and non-aliquot corners lying between grid designations, mark the appropriate grid area with a dot and use the index code to the north and west (local systems may be used if the method is approved by the County Surveyor or Clerk and a written description of its use is filed in the front of each book of certificates).

## **Cross Index Plat**



## State Plane Coordinates (optional)

Zone	W	WC	EC	E	feet/meters	
☐ NAD	1927		□NG	/D 1929	NAD 1983	NAVD 1988
North (Y) =	<u> </u>			East (X) =		EL =
Latitude					Longitude	1515 =
Scale Factor		<u></u>			Geoid Height	

#### Certification

IJohn A. Steil		Wyoming PLS	: 2500	
that I, or others under r	my supervision, have performed the wo	wk ne does it sit a		certify
	Steil Surveying Services	ak as described above and	I completed this	form.
Mailing Address	P.O. Box 2073			
Street Address	200 E. 8th Ave.		A. A.	
City, State, ZIP	Cheyenne, WY 82003	100	O. C.	47 47
Telephone, FAX	307-634-7273		/ <b>4</b> // 1.3	· \
			PL 1	J.
		ر ک	7	

Signature, Seal, and Date

Sheet \_\_\_\_ of \_