State of Wyoming Corner Record

(in compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1977, Section 36—11—101, et. seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if comer is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this comer. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (If determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

GLO RECORD:

RECORD UNKNOWN.

MONUMENT FOUND:

NOTHING FOUND.


MONUMENT SET:

SET A 5/8" X 24" REBAR WITH A 2 1/2" ALUMINUM CAP DOWN 0.4' BELOW GROUND SURFACE. CAP STAMPED AS SHOWN BELOW.

CAP STAMPED AS SHOWN BELOW


REFERENCES:

MONUMENT LIES AT THE INTERSECTION OF FOUR PLOWED FIELDS WITH A $1/4^{\circ}$ X 4' FIBER GLASS ROD 0.5' WEST OF SET MONUMENT. NO NEARBY OBJECTS TO REFERENCE TO.



Date of Field Worlc 6-1-98

Office Reference: 98135



Firm/Agency, Address

STEIL SURVEYING SERVICES,LLC.

1102 WEST 19th STREET

CHEYENNE WY 82001

Telephone Number: (307) 634-7273

This corner record was prepared by me or under my direction and supervision.

SEAL & SIGNATURE



BOOK 1524 Corner Nome: <u>EAST 1/4</u> SBRPEPLS/PLSW: Morch 1994

_Section: <u>32 T 13N R 62W ; 6th</u> P.M. Cross-Index No.: <u>X-9</u>

0584