## State of Wyoming Corner Record


(In compliance with the CORNER PERPETUATION AND FILING ACT, Wyoraing Statutes, 1997, Section 33-29-140 et. seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found nd/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points ith course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

## Record:Set Granite Boulder 23 x 9 x 5

Found:  $3\frac{1}{4}$ " Aluminum cap on  $2\frac{1}{2}$  Aluminum pipe inscribed as shown below Location of monument



**Corner Ties Detail** 



**Cap Stamping Detail** 


Mustang Ridge Subdivision Fenceline in good condition Fenceline in poor condition 17 20 ocation of Section **Corner Monument** 

Vicinity Map

April 2002 Date of Field Work:\_

Office Reference: 2310 - Storey Blvd

## CROSS INDEX DIAGRAM



Firm/Agency, Address

Washington Infrastructure Services

5920 Yellowstone Road

Cheyenne, Wyoming 82009

Telephone Number: 307-634-1101

This corner record was prepared by me or under my direction and supervision.

SEAL & SIGNATURE

NE Section 20

SBRPEPLS/PLSW:March 1994; PLSW January 1998

Section: 20 T 14N R 66W; 6th

P.M. Cross-Index No.: N-9

RECORDED 12/19/2002 AT 1:54 PM REC# 339040 3K# 1691 PG# 1393

