State of Wyoming Corner Record


(In compliance with the CORNER PERPETUATION AND FILING ACT, Wyomin's Statutes, 1997, Section 33-29-140 et. seq., and the Rules and Regulations of the oard of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.


Record of original survey and citation of source of historical information (if comer is lost or obliterated). Description of corner monumentation evidence found nd/or monument and accessories established to perpetuate the location of this comer. Sketch of relative location of monument, accessories, and reference points ith course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated comer.

Record:Set Granite Boulder 17 x 10 x 6

Found: Damaged 2" Aluminum cap with inscription worn off as shown below



Corner Ties Detail



Cap Stamping Detail

Vicinity Map 2310 - Storey Blvd

April 2002 Date of Field Work:

CROSS INDEX DIAGRAM

Firm/Agency, Address Washington Infrastructure Services 5920 Yellowstone Road

Office Reference:

Cheyenne, Wyoming 82009 Telephone Number: 307-634-1101 This comer record was prepared by me or under my direction and supervision.

SEAT & SIGNATURE



W 1/4 Corner of Section 20 SBRPEPLS/PLSW:March 1994; PLSW January 1998

된

Section: 20 T 14N R66W; 6th P.M. Cross-Index No.: P-5

