
State of Wyoming Corner Record

(In compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1997, Section 33-29-140, et seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

SECTION CORNER: 2,3,10, and 11, TIZN, ROW, 6TH PM, LARAMIE COUNTY, WYOMING FOUND: 2.5" ALUMINUM CAP SET BY PLS #4522 IN 2011




Date of Field Work: June 2nd 2018

CROSS INDEX DIAGRAM

Office Reference:

#61499



Land Surveyor / Firm / Address

This corner record was prepared by me or under my direction and supervision.

TAUL DEGRAFE PLS \$ 16041 and supervision.
SEAL & SIGNATURE

ENCOMPASS ENERGY SERVICES, LLC

350 INTERLOCKEN BLVO. SUITE 350

BROOMFIELD CO 80021

Telephone: 303 - 955 - 6080

Date O MING

Corner Name: SOUTHEAST SECTION CORNER Section: 3 T 12N R 6W; 6TH P.M. Cross-Index No.: E - 17 SBRPEPLS/PLSW: March 1994; PLSW January 1998



RECP #: 738325

RECORDED 9/5/2018 AT 12:57 PM BK# 2595 PG# 764 Debra K. Lee, CLERK OF LARAMIE COUNTY, WY PAGE 1 OF 1