## CERTIFIED LAND CORNER RECORDATION

## DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (If known)


G.L.O. Retracement survey accepted 28 May 1913 by the Surveyor General, of T12N., R62W.6th PM calls for  $l^{\prime\prime}$  dia iron pipe with a brass cap.

## DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Found monument as described 1.3 ft below the surface of County Road 150. The iron pipe was bent towards the North. Set 32" long No 5 rebar on the South side of the monument as shown. The rebar, as shown, has an aluminum cap marked as a witness corner and burried approximately 0.4 ft below road surface.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNER IF DETERMINED IN THIS SURVEY.

(May Sketch or Paste Reproduction on Reverse Side.)



done on the diagrammed corner as reported on this re	certify that I have carefully perform	ned or reviewed the work
	Larry T. Perry Signature of Surveyor	£.5.3047 Registration No.
STATE OF WYOMING,		
Office of Clerk and Recorder, County of <i>January</i>		6.78290
This "corner record" was filed for record on the on the cross-index plat and is assigned page No.		, 19, was noted
	Your C Whitehealdy Office	ai
	Cross Index NoT	R <i>N</i> er.
		R Ker. R Mer.
	T	R
	T	R. <u> M</u> er.

CB+ TARGO