CERTIFIED LAND CORNER RECORDATION DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (If known) LOCATION No evidence of corner monument found. Corner position re-established by proportionate measurement. S.10 S.11 G.L.O. reocrd - Sandstone, 16" x 9" x 4" - 1874. T.12N., R.64W. 6th P.M. DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER: At the corner: Set a $1\frac{1}{2}$ " dia. x 30" long (concrete-filled) iron pipe with brass cap. Placed old tire (rock-filled) around corner monument. Accessories: SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNER IF DETERMINED IN THIS SURVEY. (May Sketch or Paste Reproduction on Reverse Side.) Basis of Bearing - By solar observation. Distances based on measurements by electronic means. ၃ *၄. င*့ိ 1/4 cor. l" = 50' Brass cap set 4" above surface. Brass cap stamped: T.12N. R.64W. S.C., Granite boulder w/ grooves S.10 S.11 LS 519 1979 R.L. Hudson certify that I have carefully performed or reviewed the work cammed corner as reported on this recordation form and approve the same. Wyoming L.S. No. 519 Signature of Surveyor Registration No. STATE OF WYOMING, 534725 Office of Clerk and Recorder, County of Janam ___day of This "corner record" was filed for record on the_ on the cross-index plat and is assigned page No...

Cross Index No. _____ T. ___ R. ___ Mer.

Cross Index No. ____ T. __ R. __ Mer.

T. ___ R. __ Mer.

Mer.

T. ___ R. __ Mer.

Photographed Indexed Assessor