State of Wyoming Corner Record

(In compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1977, Section 36-11-101, et. seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

FOUND: GRANITE STONE 17'x10'x6"

SET: 34 CAP ON 28" ALUMINUM PIPE STAMPED AS SHOWN

STONE BURIED ALUNGSIDE

REFERENCES SET: P.K. NAIL WITH WASHER STAMPED LS 566 IN FENCEPOSTS

G.L.O RECORD: SANDSTONE 13'x12"x8"

T 12 N

14 - 2

11

R 66 W

PLS 566

X X GATE D X X X

GATE

TO NW Sec II

CHEXE IN PENCEPOST


CHEXE IN PENCEPOST

CHEXE II

CH

Date of Field Work: 19 July 1995 Office Reference: 2831

CROSS INDEX DIAGRAM



Firm/Agency, Address

Section:

INTERMOUNTAIN PROFESSIONAL SERVICES, INC. 5801 OSAGE AVENUE CHEYENNE WY 82001

Telephone Number: (307) 632-3138

This corner record was prepared by me or under my direction and supervision.

SEAL & SIGNATURE

Side Survey D. Brance Date Survey 9 1996

T12N R46N; 6 P.M. Cross-Index No.: E-19

BOOK 1432

Corner Name: