State of Wyoming Corner Record

(in compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1977, Section 36-11-101, et. seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner manumentation evidence found and/or manument and accessories established to perpetuate the location of this corner. Sketch of relative location of manument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of last or obliterated corner.

GLO RECORD: RECO

RECORD UNKNOWN.

MONUMENT FOUND:

NOTHING FOUND.


MONUMENT SET:

SET A 5/8" X 24" REBAR WITH A 3 1/4" ALUMINUM CAP DOWN 0.5' BELOW GROUND SURFACE. CAP STAMPED AS SHOWN BELOW.

CAP STAMPED AS SHOWN BELOV


REFERENCES:

MONUMENT LIES ON THE SOUTH TRACK OF A TWO TRACK ROAD. SET 5/8" X 24" REBAR WITH 1 1/2" ALUMINUM CAPS FOR REFERENCE. NO NEARBY OBJECTS TO REFERENCE TO. REFERENCES ARE SHOWN BELOW.



Date of Field Work: 6-1-98

Office Reference: 98135



Firm/Agency, Address

STEIL SURVEYING SERVICES,LLC.

1102 WEST 19th STREET

CHEYENNE WY 82001

Telephone Number: (307) 634-7273

This corner record was prepared by me or under my direction and supervision.

SEAL & SIGNATURE



Corner Norne: NE SECTION CORNER
SBRPEPLS/PLSW: March 1994

Section: 32 T 13N R 62W ; 6th P.M. Cross-Index No.: V-9

0581