
State of Wyoming Corner Record


(in compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1977, Section 36-11-101, et. seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)


of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

FOUND 2" ALUMINUM CAR LS 2927 MARKED AS SHOWN.







Date of Field Work: 12-12-94

Office Reference:

CROSS INDEX DIAGRAM

Firm/Agency, Address

STEIL SURVEYING SERVICES 1102 WEST 19th STREET 82001 CHEYENNE

This corner record was prepared by me or under my direction and supervision. SEAL & SIGNATURE

Telephone Number: <u>(307)</u> 634-7273

filled in 13/44



1396

Section: 9 T/3N RG3W 6 Th. P.M. Cross-Index No.: 14-9

0752