

State of Wyoming Corner Record

(In compliance with the *CORNER PERPETUATION AND FILING ACT*, Wyoming Statutes, 1997, Section 33-29-140, et. seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

G.L.O. Record: Unknown


Subsequent Records: Certified Land Corner Recordation filed June 27, 1983, by Mr. Ed Fry indicates a cross identified as "W 1/4 Sec. 31"

Record of Survey, not of record, undated and performed by Steil Surveying Services titled "Record of Survey For Karen Franzen" indicates a found iron pipe at the corner location.

Found: At the measured distances on the Mr. Fry Certified Land Corner Recordation noted above and at the noted distances and iron pipe on the Steil Surveying Services Record of Survey noted above, I found a 1" x 29" iron pipe, 0.2' below natural ground surface.

Set: At the found iron pipe, I set a No. 5 x 48" rebar with 2 1/2" diameter aluminum cap, marked as noted below, 0.2' below natural ground surface.


Aluminum Cap Markings



Date of Field Work: July, 2006

Office Reference: Edith Lang Family Trust

CROSS INDEX DIAGRAM



Firm/Agency, Address

Paul A. Reid, PLS
1533 Pinion Drive
Cheyenne WY 82001
Phone: (307) 637-3400

This corner record was prepared by me or under my direction and supervision.

SEAL & SIGNATURE



Corner Name: East 1/4 Section: 36 T.13N., R.63W., 6th P.M.,
SBRPEPLS/PLSW: MARCH 1994/97

Cross-Index No.: X-25