CERTIFIED LAND CORNER RECORDATION

LOCATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (If known)


R 513 518 R

Location is in area worn away by an existing road. No evidence of original corner found.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Set % rebar and alum cap
Corner determined by intersection of south lines
of Sections 13 918 and east line of Section 13
between found corners

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNER IF DETERMINED IN THIS SURVEY. (May Sketch or Paste Reproduction on Reverse Side.)



1/4 0 stone c alam cap	
I, Francis J. Thornton certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. Figure 1. Thornton certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. Figure 1. Signature of Surveyor Registration No.	
STATE OF WYOMING, Office of Clerk and Recorder, County of This "corner record" was filed for record on thedo on the cross-index plat and is assigned page No	