State of Wyoming Corner Record

CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1997 Section 33-29-140 et. seq., and the Rules and Regulations of the Board of Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

LOCATION: Northeast Corner of Section 23, T13N, R66W, 6th Principal Meridian, Laramie County.

RECORD: GLO - Set a Granite Boulder 18"x10"x4"

> 1990 - William Armstrong, PELS 3153, filed a corner record stating that he found a brown stone 5"x9"x7" well set with 3 chisel marks on south face, 1 chisel mark on east face. Set an aluminum cap on a 5/8"x24" rebar on north side of stone as an accessory. (Measured 2637.98' to the WQ corner of Sec. 13, measured 2635.98' to the SQ of Sec. 14)


2010 - Lawrence C. Kay, LS 489, found a set marked sandstone which measures 0.7' east and west by 0.5' north and south and protrudes above the ground 0.5'. There are 3 notches on the south face, 1 notch on the east face. (Measured 2631.88' to the NQ corner of Sec. 24, measured 2638.04' to the EQ corner of Sec. 14)

RECOVERED: Westwood Professional Services searched area found a disturbed 14"x9"x7" stone with 3 notches on south face and 1 notch on east face. Also found a 1.25" aluminum capped monument stamped "PELS 3153" that was 3.2' west of the stone. Distance to disturbed stone does not match to the SQ of Sec. 13 from the corner record filed by Lawrence C. Kay, doc. #568292. William Armstrong in 1990 filed a corner record on this corner (Book 1322 Page 964) and set an aluminum cap on north side of the stone.

R66W S14 S13 19 90 S23 S24 PELS 3153

Monument Inscription

RESET: Westwood Professional Services moved the disturbed stone back to its original location which is the south side of the aluminum cap.



Date of Field Work: 7/1/2019

Office Reference: 22237.00

Cross Index Plat

Firm/Agency, Address

Westwood Professional Services 3701 12th St. N. Ste. Cloud, MN 56303

This corner record was prepared by me or under my direction and supervision.

SEAL & SIGNATURE

(320)-253-9495 Telephone Number:

ossional Land

RECP #: 771555 RECORDED 2/13/2020 AT 10:16 AM BK# 2659 PG# 931 Debra K. Lee, CLERK OF LARAMIE COUNTY, WY PAGE 1 OF 1

Corner Name Northeast Corner Section 23, T 13 N, R 66 W, 6th P.M.

County: Laramie Wyoming

Cross-Index No.: N-21

SBRPEPLS/PLSW: March 1994; PLSW January 1998