## CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (If known)

LOCATION

Found broken 6"  $\times$  12"  $\times$  24" Granite stone, plainly marked with 1 notch on South edge and 3 notches on East edge, bottom portion firmly set.

S.28 S.27

S.33 S.34

T.13N., R.67W. 6th P.M.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

No ties available.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNER IF DETERMINED IN THIS SURVEY.

(May Sketch or Paste Reproduction on Reverse Side.)

FD. GRANITE STONE, 24"x 12"x6",
BROKEN, PLAINLY MARKED W/I
NOTCH ON SOUTH EGDE, 3
GROOVES ON E. FACE, BOTTOM
PORTION FIRMLY SET.

33

1, JOHN A. STEIL	certify that I have carefully	performed or reviewed the work
done on the diagrammed corner as reported on this		
	John A. Si	teil 2500
· .	Signature of Surveyor	Registration No.
STATE OF WYOMING,	• .	
Office of Clerk and Recorder,		<b>568011</b>
County of Janamie		
This "corner record" was filed for record on the	_day ofFEB1	5 1980 , 19 , was noted
on the cross-index plat and is assigned page No	•	•
		Year-C Whitehead
• •	Cou	nty Official
	Cross Index No	T R Mer.
	V13	T/_3 R67 Mer.
		T R Mer. T R Mer.
		T R Mer.
	·	T R Mer.
		T R Mer.
V-13 13	' <b>~6</b> 7	