**State of Wyoming Corner Record** 

(In compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1997, Section 33-29-140, et seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)


Reverse side of this form may be used if more space is needed.


Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

Section Corner: Sections 28, 29, 32 & 33, T14N, R61W, 6th PM, Laramie County, Wyoming

## **GLO record:**

Found: No evidence of original GLO monument; 3" Al. Surv Cap properly stamped with "PLS 15262". Accepted as best available evidence of the original position, and as the historic basis of current surveys in alignment with evidences of occupation. I was familiar with this corner as described under the previous Corner Recordation form filed under PELS No. 347. And this current corner monument is located within the same hole in the asphalt paving. I assume the previous survey cap was dislodged and the current cap was set upon the previously set rebar found still in place. No Corner Recordation





Land Surveyor / Firm / Address

John J. Studley, PLS No. 4828

615 West Dale Blvd

Cheyenne, WY 82001

Telephone: <u>307-287-4755</u>

This corner record was prepared by me or under my direction and supervision. SEAL & SIGNATURE

