## CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (If known)

LOCATION Found a 5/8" dia. rebar, 0.8 foot below graded road surface,

S.11 S.12

S.14 S.13 A 1/2" dia. iron pipe bears N 45<sup>0</sup>33' E, 56.41 feet distant.

T.14N., R.64W. G.L.O. record - Granite boulder, 22" x 10" x 4" - 1871. 6th P.M.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At the corner: No additional monumentation.

Accessories: None set.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNER IF DETERMINED IN THIS SURVEY.

(May Sketch or Paste Reproduction on Reverse Side.)

Basis of Bearing: By solar observation, one-half mile east of this corner. Distances based on measurements by electronic means.



LAKO \_\_certify that I have carefully performed <del>or reviewed</del> the work R.L. Hudson e on the diagrammed corner as reported on this recordation form and approve the same. 05 VI S. No. 519 Wyoming L Registration No. STATE OF WYOMING, Office of Clerk and Recorder, 534731 County of Yanamil This "corner record" was filed for record on the \_\_\_\_\_day of on the cross-index plat and is assigned page No.\_\_\_\_, in book No.\_\_\_\_, County Official Cross Index No 64 R. R. . \_ T. . R. \_ T. . . R. Mer. \_ R. \_ . T. . \_ T. \_ \_ R. \_

J-21 14-64