## **CERTIFIED LAND CORNER RECORDATION**

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (If known)

Found a 5/8" dia. rebar, 0.4 foot below graded road surface, LOCATION

origin unknown. S.14 S.13

G.L.O. record - Granite boulder, 20" x 12" x 6" - 1871. S.23 S.24

T.14N., R.64W. 6th P.M.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the corner: No additional monumentation.

Set a 5/8" dia. x 24" long rebar with aluminum cap; bears N  $45^{\circ}11'$  E, 56.37 feet distant; stamped R.P. TO S.C. Accessories:

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNER IF DETERMINED IN THIS SURVEY.

(May Sketch or Paste Reproduction on Reverse Side.)

Basis of Bearing: By solar observation, one-half mile east of this corner. Distances based on measurements by electronic means.

Q1/4 cor.

	2000 A				Bahan w/	7
S.C.	589°3	6'42" E	1,310.08'	—0 W I/16 cor., cap, LS 5	reborw/ 19	
COUNTY	ROAD	12 - G				1" = 40'
CISTE CONT	60. RD.					

R.L. Hudson certify that I have carefully performed or reviewed the work ne on the diagrammed corner as reported on this recordation form and approve the same.

.519

Wyoming L S. No. 519 Registration No. Signature of Surveyor

STATE OF WYOMING,

534733

Office of Clerk and Recorder, County of Varamia

This "corner record" was filed for record on the \_\_\_\_\_day of . on the cross-index plat and is assigned page No.\_\_\_\_, in book No.\_\_\_\_,

> County Official Cross Index No. N. 21 R. T.

Mer. Mer. \_ T. . R. T. . . R. Mer.

\_ R. \_ \_ T. \_ \_ T. \_ \_ R. \_

14-64 N-21