State of Wyoming Corner Record


(In compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1997, Section 33-29-140 et. seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

Record: 2" Brass Cap LS 519 S 1/16 20/21

Found: 2" Brass Cap Steel pipe as shown below



See attached sheets for phototgraphic views of the area surroundiing



Cap Stamping Detail

Vicinity Map

Date of Field Work:

April 2002

Office Referenc:

2310 - Storey Blvd


-3.5--34-10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25



Infrastructure Services **5920 Yellowstone Road** Cheyenne, Wyoming 82009 307-634-1101

This corner record was prepared by me or under my direction and supervision.

SEAL & SIGNATURE




Corner Name: S 1/16Section 20/21


Section: 20

T{14N}____


P.M. Cross-Index No.: Q-9

___:6th











20

14N

66W