State of Wyoming Corner Record

(in compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1997, Section 33—29—140, et. seq. and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.


Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.


FOUND: #5 rebar at 1/4 corner location on 12/98

Destroyed during road re-construction.

G.L.O. RECORD: Lime Stone 22" x 10" x 4" (1870)

Set 3 1/4" dia. Aluminum Cap on #5 x 24" rebar 4-6" under asphalt & core placed on top. at found monument location. Corner position was established or re-established during a pre-construction boundary survey completed 6/99 for WYDOT under Job No. CMU-1100(15) & SET: CMW-211(5) with a Project Scale Fator of 1.000360959, using a pre-determined coordinated system provided by WYDOT to determine coordinate postions. Map of Survey recorded 6/99.





This corner record was prepared by Craig M. Cowley under my direction and supervision.

SEAL & SIGNATURE



12/08/2004 AT 2:05 PM REC# 404477 3K# 1852 PG# 1688

15N T 14N R 67W; 6th P.M. Cross-Index No.: Z-15 1/4 CORNER Corner Name: 1/4 CO SBRPEPLS/PLSW: March 1994