

State of Wyoming Corner Record




(In compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 2013 Section 33-29-901 through 33-29-910, and the Rules and Regulations of the Board of Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.


FOUND: #6 REBAR WITH 3-1/4" ALUMINUM CAP, 0.5' BELOW GRADE IN CENTER OF ROAD, "PLS 2500". MEASURED TIES AS SHOWN.

Legend



-  MONUMENT FOR THIS CORNER RECORD
-  FOUND ALUM CAP
-  FOUND STONE MONUMENT

BEARINGS FROM GPS GRID UTM83 ZONE 13

DISTANCES ARE GPS GRID



Monument location




Monument Inscription

Date of Field Work: SEPT. 2019

Office Reference: JOB NO. 61962

Cross Index Plat




Firm/Agency, Address

Paul E. DeGraff
Encompass Energy Services
1954 E. Richards St. Suite 8
Douglas, Wyoming 82633
 Telephone: (303) 995-6080

This corner record was prepared by me or under my direction and supervision.

SEAL & SIGNATURE



RECP #: 772705
 RECORDED 2/28/2020 AT 3:30 PM BK# 2661 PG# 1389
 Debra K. Lee, CLERK OF LARAMIE COUNTY, WY PAGE 1 OF 1

Corner Name E 1/4 Corner Section 10, T 15 N, R 63 W, 6th P.M.

Cross-Index No.: G-17