State of Wyoming Corner Record

(in compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1977, Section 36—11—101, et. seq., and the Rules and Regulations of the Board of Registration for Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.


Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

GLO RECORD: UNKNOWN.

MONUMENT FOUND: NOTHING FOUND.

SET 5/8" X 24" REBAR WITH 2" ALUMINUM CAP. CAP STAMPED AS SHOWN BELOW. REBAR AND CAP DRILLED INTO ROCK. MONUMENT SET:

REFERENCES: REFERENCES SHOWN BELOW.



Date of Field Work: 1-3-96

Office Reference:_ 95131

CROSS INDEX DIAGRAM Firm/Agency, Address

STEIL SURVEYING SERVICES,LLC. 1102 WEST 19th STREET

WY 82001 CHEYENNE

Telephone Number: (307) 634-7273

Sesional Land Surveyor

This corner record was

direction and supervision. SEAL & SIGNATURE

prepared by me or under my

Corner Name: NORTH 1/4 SBRPEPLS/PLSW: March 1994

Section: 31 T 15N R 70W; 6th P.M. Cross-Index No.: V-3

0576