Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for reestablishment of lost or obliterated corner.

GLO RECORD: NO RECORD.

MONUMENT FOUND: NOTHING FOUND.

SET 5/8" X 24" REBAR WITH 2" ALUMINUM CAP. CAP STAMPED AS SHOWN BELOW. MONUMENT SET: ნ

REFERENCES: REFERENCES SHOWN BELOW.

글 NORTH CROW ROAD SET 60d NAIL IN PINE PINE ROCK **OUTCROP** SET 60d 80 NAIL 2" AL. CAP 555 E 1/16 NORTH CROW **ROAD** 1996 59

Date of Field Work: 1-3-96

<u>95131</u> Office Reference:

CROSS INDEX DIAGRAM

Firm/Agency, Address

STEIL SURVEYING SERVICES,LLC. 1102 WEST 19th STREET CHEYENNE WY *82001*

Telephone Number: <u>(307)</u> 634-7273

This corner record was prepared by me or under my direction and supervision. SEAL & SIGNATURE

Sessional Land Surveyor

EAST 1/16 Corner Name: EAST 1/16 SBRPEPLS/PLSW: March 1994 Section: 30 T 15N R 70W; 6th P.M. Cross-Index No.: V-4

0577