State of Wyoming Corner Record

(In compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1997 Section 33—29—140 et. se., and the Rules and Regulations of the Board of Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (If determined in this survey). Method and rationale for re—establishment of lost or obliterated corner.

RECORD: G.L.O. survey by Henry G. Hay in 1873; "80.00 ch: a Limestone 24x16x7 set 18 inches deep marked with 5 notches on east and 2 notches on south"

FOUND: No evidence of marked stone. A north-south fence is 41 feet east, did not accept this fence, computed position by double proportion from section corners N-S-E-W.

Re-monumentation: Set 2.5" Alum. cap on 3/4"x30" rebar 0.2 above ground, set T-Post 1.0 ft. north.


NAD83, position:


| Point # | North | East | Elev. |
|---------|-----------|-----------|---------|
| 1860302 | 368078.44 | 944869.92 | 4951.98 |

NOTE: After extensive work in this township I found many corner stones moved & wired to fences in low areas.

NOTE: BEARINGS AND DISTANCES SHOWN HEREON ARE BASED UPON GRID USING NAD83 WYOMING EAST ZONE AND TRIMBLE R8 GPS OBSERVATION

Monument Location





Date of Field Work: May 15, 2019

Office Reference: DRG-21884, Pt.1860302

