State of Wyoming Corner Record

(in compliance with the CORNER PERPETUATION AND FILING ACT, Wyoming Statutes, 1997 Section 33—29—140 et. se., and the Rules and Regulations of the Board of Professional Engineers and Professional Land Surveyors)

Reverse side of this form may be used if more space is needed.

Record of original survey and citation of source of historical information (if corner is lost or obliterated). Description of corner monumentation evidence found and/or monument and accessories established to perpetuate the location of this corner. Sketch of relative location of monument, accessories, and reference points with course and distance to adjacent corner(s) (if determined in this survey). Method and rationale for re—establishment of lost or obliterated corner.

RECORD: G.. L. O. survey Alfred M. Rogers in 1873: "80.00 chs, set 18x12x7 Limestone 5 inches deep, marked marked 2 notches on south and 2 notches on east"

FOUND: no evidence...

Re-monumentation: By double proportion, set 2.5 aluminum cap on 5/8x24 inch rebar with cap 0.2ft above ground.


NAD83, position:

Point #	North	East	Elev.
1861272	367972.28	929244.37	4831.05

NOTE: After extensive work in this township I found many corner stones moved & wired to fences in low areas. There is minimal section control!

NOTE: BEARINGS AND DISTANCES SHOWN HEREON ARE BASED UPON GRID USING NAD83 WYOMING EAST ZONE AND TRIMBLE R8 GPS OBSERVATION

Monument Location



Date of Field Work: April 28, 2019

Office Reference: DRG-21744, Pt.1861272

