REVENTE LARAMIE COUNTY CHEYENNE, WY.

CERTIFIED LAND CORNER RECORDATION 90 NOV 30 AM 11 57

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (If known)

No evidence of corner found. Original record - Set sandstone 22x11x3

> DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


. 13 18 LS 601

24 19

Set 5/8"x18" rebar with aluminum cap stamped built mound of rocks around corner.

Corner was considered lost so re-established by single proportion on N-S range line between corner to Sections 12, 7, 13 and 18 and Quarter corner between Sections 24 and 19.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNER IF DETERMINED IN THIS SURVEY. (May Sketch or Paste Reproduction on Reverse Side.)



I, James E. Greer done on the diagrammed corner as reported on this reco	24 19 1/4 Cor	eviewed the work
	Signature of Surveyor	LS 601 Registration No.
STATE OF WYOMING, Office of Clerk and Recorder, County of Laramie		·
This "corner record" was filed for record on theday on the cross-index plat and is assigned page No,	in book No	2, was noted 2, was noted 2, Mer. 6ti 2, Mer. 6ti 3, Mer. 8, Mer. 8